



Elliott Duchon, Superintendent  
 4850 Pedley Road, Jurupa Valley, CA 92509 T 951.360.4100

Date: January 31, 2020

Re: 19-20-05TE - Network Equipment (E-Rate Year 23) – Addendum #1

TO ALL BIDDERS:

The following clarifications to the Bid Documents shall apply to proposals made for the above referenced project. All parties of interest shall take careful note of the addendum so that the proper allowances may be made in strict accordance with the Addendum.

***Bidder shall acknowledge receipt of this addendum in the space provided on the Bid Form. Failure to do so may subject Bidder disqualification.***

In case of conflict between bid documents and this addendum, this addendum shall govern.

| Subject/item | Question   | Answer  |
|--------------|--|---|
| C9500        | For the C9500 switch, the C9500-NW-A-EDU license is not available, only the C9500-NW-A-L-EDU (which is low density not high density). Is that okay?                                  | C9500-NW-A-L-EDU is the correct license for the C9500-40X-EDU.<br><a href="https://apps.cisco.com/coreui/public/app/productui/productconfig.jsp?rl=y&amp;appid=BNP&amp;sId=1580361450611&amp;plp=Y&amp;pid=5e3266eaf3d1ad397fa80bd1#reloaded">https://apps.cisco.com/coreui/public/app/productui/productconfig.jsp?rl=y&amp;appid=BNP&amp;sId=1580361450611&amp;plp=Y&amp;pid=5e3266eaf3d1ad397fa80bd1#reloaded</a> |
| S9500-UK9    | The Software image for the C9500 switch will be S9500UK9-169 instead of -166. Is that okay?  | Per the Cisco Configuration tool, S9500UK9-1612 is the most updated image applied to the C9500-40X-EDU switch.  |
| SMARTNET     | Do you want SMARTnet included for the C9500 or C9300 switches? Term? SW NO RMA or something else?  | We are not requesting SMARTNET coverage.  |
| CAB-TA-NA    | The request for 180 Power Cables (CAB-TA-NA) is made up of 40 included with the C9500's, 138 included from C9300's and 2 stand-alone. Is that okay or do you just need 178 included? | Please provide only the 178 CAB-TA-NA that are included with the equipment. As these are included, this is a no cost change clarification.  |
| C9300        | For the C9300 image, it will be S9300UK9-1611 instead of -166. Is that okay?   | Per the Cisco Configuration tool, S9300UK9-1612 is the most updated image applied to the C9300-40U-EDU switch   |

**LEARNING WITHOUT LIMITS**